

Community Development Department • Building Inspection Division 500 Castro Street • Post Office Box 7540 • Mountain View, California 94039-7540 • 650-903-6313 • FAX 650-903-6474

## **SKYLIGHT FRAMING DETAIL Roof Framing Around Openings**

- Headers with a span exceeding 4' must be framed with trimmers and header rafters that are doubled or of lumber of equivalent cross-section.
- The ends of header rafters more than 6' in length shall be supported by framing anchors or rafter hangers unless the rafters bear on a beam, partition or wall.

